

[Print This Page](#)

## Inspection Results by Operator

Date Range: 03/08/15 - 03/13/15

Location: -- All --

Department: -- All --

03/13/15 08:14:21 AM CDT

User: 1

Role: -- All --

Shift: -- All --

No.	Question	Expected Answer	Answer Received	Pass / Fail	Generated Lock
Gauna, Harry                      Role: DEF-EQUIP-OPRTR                      Department: Handles                      Shift: 1st					
FC	15 - 7FBEU15-21919				

1	Leaks Any Visible?	No	No	Passed	No
2	Tires & Wheels In Good Condition?	Yes	Yes	Passed	No
3	Forks In Good Condition?	Yes	Yes	Passed	No
4	Safety Devices Any Malfunctioning?	No	No	Passed	No
5	Chains, Cables Hoses Any Visible Damage?	No	No	Passed	No
6	Steering Proper with No Binding or Issue?	Yes	Yes	Passed	No
7	Travel Controls Any Problems?	No	No	Passed	No
8	Brakes Stop in Proper Distance?	Yes	Yes	Passed	No
9	Hydraulic Functions Any Malfunctioning?	No	No	Passed	No
10	Are You a Safe Driver?	Yes	Yes	Passed	No
11	Is the equipment safe to operate?	Yes	Yes	Passed	No
Location: The Libman Company		Inspection Type: Inspection Passed		Questions Failed: 0	
Completed: 03/09/15 07:23:41 AM CDT		Elapsed Time: 00:00:33		Lock Generated: No	

No. Inspections: 1  
Ave. Elapsed Time: 00:00:33

Questions Failed: 0  
Lock Generated: No

No. Inspections: 1

Questions Failed: 0

Powered By

InfoLink

1 of 1